



# TEST REPORT

## (시험성적서)

신청기관 (인) : 한국 다이요 잉크  
Applicant : TAIYO INK MFG. CO., (KOREA) LTD.

주소 (한글) : 경기도 안산시 단원구 신길동 1058-8  
Address (Engl.) : 1058-8, Singil-dong, Danwon-gu,  
Ansan-city, Gyeonggi-do, Korea

발행면수 (Page) : 1 of 3  
발행일자 (Date) : 2013. 01. 14.

시험성적서 번호 (Report No.) : RT13R-S0121-002-K2

시료 명세 : 시료에 대한 상세한 정보는 아래와 같음  
(Sample Description) (The following submitted sample(s) said to be)

제품명/형식 : S-200 Y5GS WITH HD-3  
(Name/Type of Product) (S-200 Y5GS WITH HD-3)

시료고유번호 : RT13R-S0121-002  
(Sample ID No.) (RT13R-S0121-002)

제품 생산자/공급자 : 한국 다이요 잉크  
(Manufacturer/Vender) (TAIYO INK MFG. CO., (KOREA) LTD.)

제출처 : 제품사용고객  
(Name of Buyer) (제품사용고객)

시료접수일자 : 2013. 01. 09.  
(Sample received) (Jan. 09, 2013)

시험일자 : 2013. 01. 09. ~ 2013. 01. 14.  
(Testing Date) (Jan. 09, 2013 ~ Jan. 14, 2013)

시험방법 : 이 시험성적서의 다음 페이지 첨부  
(Test Method) (Please see the following page)

시험결과 : 이 시험성적서의 다음 페이지 첨부  
(Test Result) (Please see the following page)

비고 (Notes) : 1. 이 시험성적서는 제시된 시료 및 시료명으로 시험한 결과로서 유사 대상시료에 적용할 수 없음.  
(The test results presented in this report relate only to the object tested.)  
2. 이 시험성적서는 승인없이 복사 사용을 금함.  
(This report shall not be reproduced except in full without the written approval of the testing laboratory.)

승인자 (Approved by)

권한자 (Authorized by)

장준용/기술책임자 (Jade Jang / Lab. Technical Manager)

박병욱/소장 (Bo Park / Lab. General Manager)

This Test Report is issued by the Company subject to its Terms and Conditions of Business printed overleaf. Attention is drawn to the limitations of liability, indemnification and jurisdictional issues defined therein. This Test Report shall not be reproduced, except in full, without prior written consent of the Company.

Intertek Testing Services Korea Ltd.

Seoul Office: Tel : 02-6090-9500 Fax : 02-3409-0026 Daegu Office : Tel : 053-600-8647 Fax : 053-600-8645 Web Site : [www.Intertek.co.kr](http://www.Intertek.co.kr)  
Seoul Lab. Address : 1/F, A-ju Digital Tower, #284-56, Seongsu 2-ga, Seongdong-Gu, Seoul, 133-833 Korea  
Ulsan Lab. Address : #340-2, Yongam-Ri, Chongryang-Myun, Ulju-Gun, Ulsan 689-865 Korea

# TEST REPORT

## (시험 성적서)

발행면수 (Page) : 2 of 3

발행일자 (Date) : 2013. 01. 14.

시험성적서 번호 (Report No.) : RT13R-S0121-002-K2

시료고유번호 (Sample ID No.) : RT13R-S0121-002

시료명 (Sample Description) : S-200 Y5GS WITH HD-3  
(S-200 Y5GS WITH HD-3)

시험항목 (Test Item)	단위 (Unit)	분석방법 (Test Method)	검출한계 (MDL)	시험결과 (Result)
브롬 (Bromine, Br)	mg/kg	With reference to EN 14582, by oxygen combustion with bomb and determined by IC	30	N.D.
염소 (Chlorine, Cl)	mg/kg	With reference to EN 14582, by oxygen combustion with bomb and determined by IC	30	416

Tested by : Nikkie Lee

Notes : mg/kg = ppm = parts per million (함량 표시 : 백만분의 일)  
 <= Less than (결과 값 이하)  
 N.D. = Not detected (< MDL, 미검출 - 검출한계 이하)  
 MDL = Method detection limit (검출한계)

\* 시료 접수 시 시료 상태 :  
(View of sample as received)



This Test Report is issued by the Company subject to its Terms and Conditions of Business printed overleaf. Attention is drawn to the limitations of liability, indemnification and jurisdictional issues defined therein. This Test Report shall not be reproduced, except in full, without prior written consent of the Company.

**Intertek Testing Services Korea Ltd.**

Seoul Office: Tel : 02-6090-9500 Fax : 02-3409-0026 Daegu Office : Tel : 053-600-8647 Fax : 053-600-8645 Web Site : [www.Intertek.co.kr](http://www.Intertek.co.kr)

Seoul Lab. Address : 1/F, A-ju Digital Tower, #284-56, Seongsu 2-ga, Seongdong-Gu, Seoul, 133-833 Korea

Ulsan Lab. Address : #340-2, Yongam-Ri, Chongryang-Myun, Ulju-Gun, Ulsan 689-865 Korea



# TEST REPORT

(시험성적서)

시험성적서 번호 (Report No.) : RT13R-S0121-002-K2


발행면수 (Page) : 3 of 3

발행일자 (Date) : 2013. 01. 14.

시료고유번호 (Sample ID No.) : RT13R-S0121-002

시료명 (Sample Description) : S-200 Y5GS WITH HD-3  
(S-200 Y5GS WITH HD-3)

## Flow Chart (Halogen)



\*\*\*\*\* End of Report \*\*\*\*\*

*This report is made solely on the basis of your instructions and/or information and materials supplied by you. It is not intended to be a recommendation for any particular course of action. Intertek does not accept a duty of care or any other responsibility to any person other than the Client in respect of this report and only accepts liability to the Client insofar as is expressly contained in the terms and conditions governing Intertek's provision of services to you. Intertek makes no warranties or representations either express or implied with respect to this report save as provided for in those terms and conditions. We have aimed to conduct the Review on a diligent and careful basis and we do not accept any liability to you for any loss arising out of or in connection with this report, in contract, tort, by statute or otherwise, except in the event of our gross negligence or wilful misconduct.*

This Test Report is issued by the Company subject to its Terms and Conditions of Business printed overleaf. Attention is drawn to the limitations of liability, indemnification and jurisdictional issues defined therein. This Test Report shall not be reproduced, except in full, without prior written consent of the Company.

**Intertek Testing Services Korea Ltd.**

Seoul Office: Tel : 02-6090-9500 Fax : 02-3409-0026 Daegu Office : Tel : 053-600-8647 Fax : 053-600-8645 Web Site : [www.Intertek.co.kr](http://www.Intertek.co.kr)

Seoul Lab. Address : 1/F, A-ju Digital Tower, #284-56, Seongsu 2-ga, Seongdong-Gu, Seoul, 133-833 Korea

Ulsan Lab. Address : #340-2, Yongam-Ri, Chongryang-Myun, Ulju-Gun, Ulsan 689-865 Korea